Identified			Percent
Year	Building Name	Building / Description	Complete
2012	Bluffsview Elementary	Interior Painting	100
2012	Bluffsview Elementary	Replace High Security Key system	100
2012	Bluffsview Elementary	Exterior Tuckpointing and Paint	100
2012	Bluffsview Elementary	Replace Chiller	100
2012	Bluffsview Elementary	Add TVSS on Switchgear	100
2012	Bluffsview Elementary	Replace Membrane Roofing	100
2012	Bluffsview Elementary	Exterior Door Security Devices	100
2012	Brookside Elementary	Replace Boiler	100
2012	Brookside Elementary	Add TVSS on Switchgear	100
2012	Brookside Elementary	Floor Tile Replacement - Classrooms	100
2012	Brookside Elementary	Floor Tile Remediation - Classrooms	100
2012	Brookside Elementary	Exterior Tuckpointing and Paint	100
2012	Brookside Elementary	Roofing	100
2012	Brookside Elementary	Exterior Door Security Devices	100
2012	Colonial Hills Elementary	Replace unitvent/AHU Systems	100
2012	Colonial Hills Elementary	Replace Chiller	100
2012	Colonial Hills Elementary	Replacement Chiller System Electric	100
2012	Colonial Hills Elementary	Add TVSS on Switchgear	100
2012	Colonial Hills Elementary	Ravine Culvert	100
2012	Colonial Hills Elementary	Carpet Replacement - Music, Library, Admin	100
2012	Colonial Hills Elementary	Refinish Interior Wood Doors	100
2013	Colonial Hills Elementary	Art Storage Room and Room 21 Renovation	100
2012	Colonial Hills Elementary	Exterior Door Security Devices	100
2012	Education Center	Replace plumbing carriers	100
2012	Education Center	Add TVSS to Switchgear	100
2012	Evening Street Elementary	Replace Domestic Water Heater	100
2012	Evening Street Elementary	Add TVSS on main Switchgear	100
2012	Evening Street Elementary	Floor Tile Replacement - Classrooms	100
2012	Evening Street Elementary	Tile Remediation - Classrooms	100
2012	Evening Street Elementary	Carpet Replacement - Music, Library, Admin	100
2012	Evening Street Elementary	Exterior Tuckpointing and Paint	100
2013	Evening Street Elementary	Replace classroom window coverings	100
2012	Evening Street Elementary	Exterior Door Security Devices	100
2012	Granby Elementary	Replace Boilers	100
2012	Granby Elementary	Add TVSS on Switchgear	100
2012	Granby Elementary	Exterior Tuckpointing and Paint	100
2012	Granby Elementary	Roofing	100
2012	Granby Elementary	Exterior Door Security Devices	100
2012	Kilbourne Middle School	160 Ton Chiller/Tower	100
2012	Kilbourne Middle School	RTU	100
2012	Kilbourne Middle School	Replace Classroom Unitvents	100

Identified Year	Building Name	Building / Description	Percent Complete
2012	Kilbourne Middle School	Replace MAU South	100
2012	Kilbourne Middle School	Replace Combustion Air Unit - Boiler Room	100
2012	Kilbourne Middle School	Install new MAU in Music Wing	100
2012	Kilbourne Middle School	Chiller System Electric	100
2012	Kilbourne Middle School	Interior Painting	100
2012	Kilbourne Middle School	Carpet Replacement - Library, Admin Areas	100
2012	Kilbourne Middle School	Exterior Tuckpointing and Paint	100
2012	Kilbourne Middle School	Roofing	100
2012	Kilbourne Middle School	Exterior Door Security Devices	100
2012	Kingsmill	Replace condensing units	100
2012	Kingsmill	Interior Painting	100
2012	Kingsmill	Flooring Replacement - Building	100
2012	Kingsmill	Illuminated flagpole	100
2012	Kingsmill	Roofing	100
2012	Kingsmill	Replace radiant heater	100
2012	Liberty Elementary School	Chilled Water Pump	100
2012	Liberty Elementary School	Replace AHU's	100
2012	Liberty Elementary School	Exterior Tuckpointing and Paint	100
2012	Liberty Elementary School	Roofing	100
2012	Liberty Elementary School	Exterior Door Security Devices	100
2012	Linworth Alternative	Exterior Tuckpointing & Paint	100
2012	Linworth Alternative	Tile Remediation - Entry Lobby	100
2012	Linworth Alternative	Flooring Replacement - Building	100
2012	Linworth Alternative	Interior Painting	100
2012	Linworth Alternative	Add TVSS on Switchgear	100
2012	Linworth Alternative	Add Computer Split/System	100
2012	Linworth Alternative	Exterior Door Security Devices	100
2013	McCord Middle School	Replace Air Compressor	100
2012	McCord Middle School	Track Structural Spray	100
2012	McCord Middle School	Carpet Replacement - Library, Admin Areas	100
2012	McCord Middle School	Exterior Tuckingpointing and Paint	100
2012	McCord Middle School	Outside storage building	100
2012	McCord Middle School	Domestic Water Heater Replacement	100
2012	McCord Middle School	Replace Boiler Expansion Tank	100
2013	McCord Middle School	Unit Vent Contols Replacement	100
2012	Outdoor Education Building	Exterior Tuckpointing and Paint	100
2012	Outdoor Education Building	Exterior Door Replacement	100
2012	Outdoor Education Building	Overhead Door Replacement	100
2012	Outdoor Education Building	Roofing	100
2012	Outdoor Education Building	Replace exterior wood siding	100
2012	Outdoor Education Building	Replace Hot water heater	100

Identified Year	Building Name	Building / Description	Percent Complete
2012	Outdoor Education Building	Ceiling Hung heaters	100
2012	Phoenix Middle School	Add TVSS on Switchboard	100
2012	Phoenix Middle School	Replace Air Compressor	100
2012	Phoenix Middle School	Ceiling Tile Replacement	100
2012	Phoenix Middle School	Interior Painting	100
2012	Phoenix Middle School	Exterior Door Security	100
2012	Phoenix Middle School	Exterior Tuckingpointing and Paint	100
2013	Phoenix Middle School	Install Cooling Tower Water Level Controls	100
2013	Phoenix Middle School	Replace Expansion Tank	100
2013	Phoenix Middle School	Control Modifications to Hot/Cold Deck AHU	100
2012	Slate Hill Elementary	Replace High Security Key system	100
2012	Slate Hill Elementary	Exterior Door Security	100
2012	Slate Hill Elementary	Exterior Tuckpointing and Paint	100
2012	Slate Hill Elementary	Roofing	100
2012	Sutter Park Elementary	Flooring Replacement	100
2012	Sutter Park Elementary	Exterior Door Security	100
2012	Sutter Park Elementary	Exterior Tuckpointing and Paint	100
2012	Sutter Park Elementary	Roofing	100
2012	Sutter Park Elementary	Add TVSS on Switchgear	100
2012	Sutter Park Elementary	Replace Des Chomps RTU	100
2012	Thomas Worthington High School	Track Structural Spray	100
2012	Thomas Worthington High School	Tennis Court Resurfacing	100
2012	Thomas Worthington High School	Asphalt Replacement / Repairs - Flats Drive	100
2012	Thomas Worthington High School	Resurface Staff parking lot	100
2012	Thomas Worthington High School	Interior Painting except corridors	100
2012	Thomas Worthington High School	InteriorPainting Business Wing Corridor	100
2012	Thomas Worthington High School	Aux Gymnasium Floor Replacement	100
2012	Thomas Worthington High School	Replace Library Carpet	100
2012	Thomas Worthington High School	Hottenroth house carpet replacement	100
2012	Thomas Worthington High School	Exterior Tuckpointing and Paint	100
2012	Thomas Worthington High School	Replace AHU's - Office/Guidance/Café RTU	100
2012	Thomas Worthington High School	Add Boiler Room pump VFD	100
2012	Thomas Worthington High School	Replace Auditorium Cooling Tower	100
2012	Thomas Worthington High School	Replace Chillers	100
2012	Thomas Worthington High School	Replace AHU 12	100
2012	Thomas Worthington High School	Replace AHU for room 161 (RTU)	100
2012	Thomas Worthington High School	Replace Air Compressor and Dryer	100
2012	Thomas Worthington High School	Replace Gym exhaust fans	100
2012	Thomas Worthington High School	Replace Café fan coil with RTU	100
2012	Thomas Worthington High School	Replace Basement VAV north and south units	100
2013	Thomas Worthington High School	Server Room Electric	100

Identified Year	Building Name	Building / Description	Percent Complete
2013	Thomas Worthington High School	Replace Public Address System	100
2013	Thomas Worthington High School	5 Ton Split System Air Conditioner	100
2012	Wilson Hill Elementary	Replace classroom window coverings	100
2012	Wilson Hill Elementary	Repave front Parking lot	100
2012	Wilson Hill Elementary	North End Parent Drop off/Bus loop	100
2012	Wilson Hill Elementary	Exterior Tuckpointing/Paint/Soffits	100
2012	Wilson Hill Elementary	Exterior Door Security	100
2012	Wilson Hill Elementary	Add TVSS on Switchboard	100
2012	Wilson Hill Elementary	Replacement Chiller System Electric	100
2012	Wilson Hill Elementary	Replace Boiler pumps	100
2012	Wilson Hill Elementary	Replace Chiller System	100
2013	Worthington Kilbourne	5 Ton Split System Air Conditioner	100
2012	Worthington Estates Elementary	Exterior Tuckpointing & Paint	100
2012	Worthington Estates Elementary	Roofing (Gymnasium)	100
2012	Worthington Estates Elementary	Exterior Door Security	100
2012	Worthington Estates Elementary	Replace Control compressor and dryer	100
2012	Worthington Estates Elementary	Replace cooling tower pump for flow	100
2012	Worthington Estates Elementary	Replace One Boiler	100
2012	Worthington Estates Elementary	Replacement Boiler System Electric	100
2012	Worthington Hills Elementary	Flooring Replacement	100
2012	Worthington Hills Elementary	Interior Painting	100
2012	Worthington Hills Elementary	Exterior Door Security	100
2012	Worthington Hills Elementary	Replace Boilers	100
2012	Worthington Hills Elementary	Replace fan coil and condenser located in boiler room	100
2012	Worthington Hills Elementary	Add TVSS on Switchgear	100
2012	Worthington Hills Elementary	Replace retractable wall between cafeteria and gym	100
2012	Worthington Kilbourne	Paint parking lot poles, tennis court poles	100
2012	Worthington Kilbourne	Ravine Soils Stabilization	100
2012	Worthington Kilbourne	Track Structural Spray	100
2012	Worthington Kilbourne	Tennis Court Resurfacing	100
2012	Worthington Kilbourne	Auditorium Carpet Replacement	100
2012	Worthington Kilbourne	Aux Gymnasium Flooring	100
2012	Worthington Kilbourne	Add TVSS on Switchgear	100
2012	Worthington Kilbourne	Replace Combustion Air Unit - Boiler Room	100
2012	Worthington Kilbourne	Replace AHU 17 Package A/C unit	100
2012	Worthington Kilbourne	Replace High Security Key system	100
2013	Worthington Kilbourne	Replace Football Lockers	100
2013	Worthington Kilbourne	Replace Exterior Stucco	100
2013	Worthington Kilbourne High School	Server Room Electric	100
2013	Worthington Kilbourne High School	Exterior Security Cameras	100
2013	Worthington Park Elementary	Replace High Security Key system	100

Identified			Percent
Year	Building Name	Building / Description	Complete
2012	Worthington Park Elementary	Paint 15 parking lot poles, 1 playground pole	100
2012	Worthington Park Elementary	Exterior Tuckpointing and Paint	100
2012	Worthington Park Elementary	Replacement Chiller System Electric	100
2012	Worthington Park Elementary	Replace Chiller	100
2012	Worthington Park Elementary	Roofing	100
2012	Worthington Park Elementary	Exterior Door Security	100
2012	Worthingway Middle School	Repair Planters	100
2012	Worthingway Middle School	Replacement Library Air Handling Unit Electric	100
2012	Worthingway Middle School	Add TVSS on Switchboard	100
2012	Worthingway Middle school	Outside storage building	100
2014	Colonial Hills Elementary	Replace Restroom Stalls	100
2014	Colonial Hills Elementary	Replace Classroom Carpeting	100
2014	Thomas Worthington High School	Replace Cardinal Theater Carpeting	100
2014	Thomas Worthington High School	Replace Adm area carpet/flooring surfaces	100
2014	Wilson Hill Elementary	Replace Carpet	100
2014	Wilson Hill Elementary	Paint Interior	100
2013	Worthington Kilbourne High School	Traffic Signal West Entry	100
2014	Worthington Kilbourne High School	Paint all interior handrails	100
2013	Education Center	Family Resource Center	100
2014	District	Seclusion Rooms	100